

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 07 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A. INC. ✓	API Number 30-025-31880 ✓
Property Name Vacuum Glorieta West Unit ✓	Well No. 105 ✓

2. Surface Location

UL - Lot N	Section 36	Township 17S	Range 34E	Feet from 453	N/S Line S	Feet From 1340	E/W Line W	County Lea ✓
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	-----------------

Well Status

TA'D WELL YES	<input checked="" type="radio"/> NO <input checked="" type="radio"/> YES	SHUT-IN NO	INJECTOR <input checked="" type="radio"/> INJ <input type="radio"/> SWD	PRODUCER OIL	GAS	DATE 2/16/16
------------------	--	---------------	--	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	✓	✓	2/A	✓	✓
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	Entered into RBDMS 2/16/16
Title: FSA	Re-test
E-mail Address: TZYR@chevron.com	
Date: 2/16/16	Phone: 575-390-4449
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 08 2016