



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA Inc.	API Number 30-025-12317
Property Name ✓ West Dellerhide Drinkard Unit	Well No. 89

2. Surface Location

UL - Lot ✓ 0	Section 38	Township 24 S	Range 38 E	Feet from 660	N/S Line S	Feet From 1830	E/W Line E	County Lea
------------------------	----------------------	-------------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ✓ YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	GAS 3/9/16	DATE 3/9/16
---------------------------	----------------------	------------------------	------------------------	----------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ			φ	1240
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Water/Dred if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Charles Stringfellow	OIL CONSERVATION DIVISION
Printed name: Charles Stringfellow	Entered into RBDMS CF
Title: FSA	Re-test
E-mail Address:	
Date: 3/9/16	Phone: 432-215-8802
Witness: Carol Flowers	

In C.F.

MAR 14 2016