



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA Inc.		API Number 30-025-12334						
Property Name ✓ West Dolar Hide Drinkard Unit		Well No. 72						
Surface Location								
UL - Lot ✓ M	Section 33	Township 24S	Range 38E	Feet from 330	N/S Line S	Feet From 660	E/W Line W	County Lea
Well Status								
TA'D WELL ✓ YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 3/9/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	ϕ		ϕ	1300
Flow Characteristics					
Puff	Y / ϕ	Y / ϕ	Y / N	ϕ / N	CO2 —
Steady Flow	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	WTR ✓
Surges	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	GAS —
Down to nothing	ϕ / N	ϕ / N	Y / N	ϕ / N	Type of Fluid
Gas or Oil	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	Injected for
Water	Y / ϕ	Y / ϕ	Y / N	Y / ϕ	WaterBond if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Carl Flowers		BS 3-11-16	
Printed name: Justin Stringfellow		OIL CONSERVATION DIVISION	
Title: FSA		Entered into RBDMS CF	
E-mail Address: ETJ@chevron.com		Re-test	
Date: 3/9/2016	Phone: 432-215-8802		
Witness: Carl Flowers			

In C.F.

MAR 14 2016