

HOBBS OCD

MAR 09 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

☒ RECEIVED		Operator Name		API Number	
✓		Chevron USA Inc.		30-025-12359	
✓		Property Name		Well No.	
		West Dollarhide Driveword unit		75	
Surface Location					
UL - Lot	Section	Township	Range	Feet from	N/S Line
✓ D	4	25S	38E	990	N
			Feet From	E/W Line	County
			330	W	Lea
Well Status					
TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE	
YES	NO	NO	NO	YES	3/9/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø			Ø	1400
Flow Characteristics					
Puff	Y / Ø	Y / N	Y / N	Ø / N	CO2
Steady Flow	Y / Ø	Y / N	Y / N	Y / Ø	WTR ✓
Surges	Y / Ø	Y / N	Y / N	Y / Ø	GAS
Down to nothing	Ø / N	Y / N	Y / N	Ø / N	Type of Fluid
Gas or Oil	Y / Ø	Y / N	Y / N	Y / Ø	Injected for
Water	Y / Ø	Y / N	Y / N	Y / Ø	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Carl Stringfellow</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Dustin Stringfellow</i>		Entered into RBDMS <i>CF</i>	
Title: <i>FSA</i>		Re-test	
E-mail Address: <i>FTVI@chevron.com</i>			
Date: <i>3/9/2016</i>	Phone: <i>432-215-8802</i>		
Witness: <i>Carl Stringfellow</i>			

In C.F.

MAR 14 2016