

HOBBS OCD

MAR 09 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name

API Number

✓ Chevron USA Inc.

30-025-12365

Property Name

Well No.

✓ Mexico L

#1

² Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
<i>✓</i> A	5	25S	38E	600	N	660	E	Lea

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
<i>✓</i> YES	NO	YES	NO	3/1/16
		Inj.	OIL	
		SWD	GAS	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>✓</i>			<i>✓</i>	<i>✓</i> vac
Flow Characteristics					
Puff	Y / <i>✓</i>	Y / N	Y / N	Y / <i>✓</i>	CO2 —
Steady Flow	Y / <i>✓</i>	Y / N	Y / N	Y / <i>✓</i>	WTR <i>✓</i>
Surges	Y / <i>✓</i>	Y / N	Y / N	Y / <i>✓</i>	GAS —
Down to nothing	<i>✓</i> / N	Y / N	Y / N	<i>✓</i> / N	Type of Fluid
Gas or Oil	Y / <i>✓</i>	Y / N	Y / N	Y / <i>✓</i>	Injected for
Water	Y / <i>✓</i>	Y / N	Y / N	Y / <i>✓</i>	Water/Dood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:

Printed name:

Title:

E-mail Address:

Date:

Phone:

Witness:

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

432-215-5802

Carl Flowers

In C.F.

MAR 14 2016