## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

HOBBS OCD

			BR	ADENH	EAD TES	T REPORT		RECI	FILE.	
			Operator Name Chevron	USI	t inc			30-025- 25	SZO	1
			Property Central Vac		1				1No.	/
				7. Sur	face Locatio	n				•
UL - Lot	Section	Township 185	Range 35E		Feet from 7450	N/S Line	Feet From ZG32	E/W Line	County Lea	V
				W	ell Status	Harris	J. Care and the			
YES TA'D	WELL	O VES	SHUT-IN		INJECTOR	SWD OIL	PRODUCER		DATE	

## **OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0	NA	0	1650
Flow Characteristics					The All Control
Puff	Y / 🕱	Ø N	Y / N	(D) N	CO2
Steady Flow	Y/69	Y/00	Y / N	Y 108	WTR
Surges	Y/(8)	Y / 🐼	Y / N	Y / 🛇	Type of Fluid
Down to nothing	Ø N	Ø/ N	Y / N	Ø/ N	Injected for
Gas or Oil	YIE	Y / 🐼	Y / N	YIQ	Waterflood if applies.
Water	YIN	Y/N	Y / N	Y/R	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

		BS 311-1	16
Signature:		OIL CONSERVATION DI	
Printed name: Tanner DeHaan		Entered into RBDMS	B
Title: FSA		Re-test	
E-mail Address: TZYR@Chevron.	com		
Date: 2-25-16	Phone: 575-390-4449		
	Witness:		