HOBBS OCD

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAR 11 2016

RECEIVED

				BRADEN	HEAD TES	T REPORT	,			
			Operator Chevro		ISA IA	1c	30	API Number	078	
Property Name Central Vacuum Unit									Well No. 139 ✓	
				7. S	urface Locatio	n				
UL - Lot	Section 36	Township 175	Range		Feet from	N/S Line	Feet From 958	E/W Line	County Lea	
					Well Status			AND AND SHARE OF		
YES TA'D	WELL	Ø YES	SHUT-IN	100	INJECTOR 5	SWD OIL	PRODUCER GAS	2-2	DATE 26-16	
				OBS	ERVED DA	TA			M	

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0	O	0	1710
Flow Characteristics				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Puff	Y/60	Y / (No	Y/80	Ø N	C02 ¥
Steady Flow	Y/60	Y/60	Y/®	Y / 🔊	WTR
Surges	Y/Ø	Y/®	Y/Ø	Y / 🔕	GAS
Down to nothing	Ø/ N	(D) N	Ø N	Ø/ N	Injected for
Gas or Oil	YIO	YIO	Y/60	Y / 🔊	Waterflood if applies.
Water	Y/60	Y/60	Y/Ø	Y/60	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

3-11-16 Signature: OIL CONSERVATION DIVISION Entered into RBDMS Printed name: Tanner DeHaan Title: FSA Re-test E-mail Address: TZYR@Chevron.com 2-26-16 Phone: 575-390-4449 Witness