

HOBBS OCD

MAR 09 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name

API Number

Chevron USA Inc.

30-025-31499

Property Name

Well No.

West Dohrwide Drinkard Unit

114

Surface Location

UL - Lot

Section

Township

Range

Feet from

N/S Line

Feet From

E/W Line

County

C

5

25S

38E

108

N

2325

W

Lea

Well Status

TA'D WELL

SHUT-IN

INJECTOR

PRODUCER

DATE

YES

NO

YES

NO

NO

SWD

OIL

GAS

3/9/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø			Ø	400
Flow Characteristics					
Puff	Y / Ø	Y / N	Y / N	Ø / N	CO2 —
Steady Flow	Y / Ø	Y / N	Y / N	Y / Ø	WTR —
Surges	Y / Ø	Y / N	Y / N	Y / Ø	GAS —
Down to nothing	Ø / N	Y / N	Y / N	Ø / N	Type of Fluid
Gas or Oil	Y / Ø	Y / N	Y / N	Y / Ø	Injected for
Water	Y / Ø	Y / N	Y / N	Y / Ø	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:

Printed name:

Title:

E-mail Address:

Date:

Phone:

Witness:

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

932-215-8602

Carol Flowers

In C.F.

MAR 14 2016