



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc.						API Number 30-005-31999			
Property Name West Dollarhide Driveway Unit						Well No. 139			
Surface Location									
UL - Lot C	Section 5	Township 25 S	Range 38 E	Feet from 420	N/S Line N	Feet From 1900	E/W Line W	County Lea	
Well Status									
TA'D WELL YES	NO		SHUT-IN NO	IN		INJECTOR NO	PRODUCER OIL	GAS NO	DATE 3/11/16

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod Csg	(E) Tubing
Pressure	$\emptyset$			$\emptyset$	625
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	N / N	Y / N	Y / N	N / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Justin Stein</i>		Entered into RBDMS <i>CF</i>	
Title: <i>FSA</i>		Re-test	
E-mail Address:			
Date: <i>3/9/2016</i>	Phone: <i>432-215-8802</i>		
Witness: <i>Carl Flaver</i>			

In C.F.

MAR 14 2016