

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
MAR 11 2016
RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON <i>USA INC</i>	API Number 30-025-32298
Property Name STATED	Well No. 3

7. Surface Location

UL - Lot M	Section 31	Township 17S	Range 35E	Feet from 330	N/S Line S	Feet From 695	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	PRODUCER OIL	DATE 3-1-2016
-------------------------	----------------------	-----------------------	------------------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>	<i>0</i>	<i>212</i>	<i>50</i>	<i>200</i>
Flow Characteristics					
Puff	Y / <i>NO</i>	Y / <i>NO</i>	Y / N	Y / N	CO2 ___
Steady Flow	Y / <i>NO</i>	Y / <i>NO</i>	Y / N	Y / N	WTR ___
Surges	Y / <i>NO</i>	Y / <i>NO</i>	Y / N	Y / N	GAS ___
Down to nothing	<i>NO</i> / N	<i>NO</i> / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / <i>NO</i>	Y / <i>NO</i>	Y / N	Y / N	Injected for
Water	Y / <i>NO</i>	Y / <i>NO</i>	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Linda Robinson</i>	OIL CONSERVATION DIVISION
Printed name: LINDA ROBINSON	Entered into RBDMS <i>CRB</i>
Title: FIELD SPECIALIST A	Re-test
E-mail Address: LRUW@CHEVRON.COM	
Date: <i>3-1-2016</i>	Phone: 575-704-2225
Witness:	

MAR 22 2016