

MAR 07 2016

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>LINN OPERATING</i>	*API Number <i>30-025-11596</i>
Property Name <i>LANGLIE MATTIX QUEEN UNIT</i>	Well No. <i>27</i>

* Surface Location

UL - Lot <i>M</i>	Section <i>14</i>	Township <i>25S</i>	Range <i>37E</i>	Feet from <i>660</i>	N/S Line <i>S</i>	Feet From <i>660</i>	E/W Line <i>W</i>	County <i>LEA</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS ☐	DATE <i>2/18/16</i>
--	--	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interf (1)	(C) Interf (2)	(D) Prod Casing	(E) Tubing
Pressure	<i>5</i>			<i>0</i>	<i>0</i>
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N
Steady Flow	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	☐ Y ☐ N
Surges	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N
Down to nothing	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	☐ Y ☐ N
Gas or Oil	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N
Water	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*(A) quick puff of gas
- down to nothing*

Signature: <i>Contreiras</i>	<i>BS 3/22/16</i>
Printed name: <i>JUNIOR CONTRERAS</i>	OIL CONSERVATION DIVISION
Title: <i>PRODUCTION SPECIALIST</i>	Entered into RBDMS
E-mail Address: <i>jcontreras@linnenergy.com</i>	Re-test <i>66</i>
Date: <i>2/18/2016</i>	
Phone: <i>575/909-0031</i>	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 23 2016

fm