Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103 Revised November 3, 2011	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-025-0570	8
811 S. First St., Artesia, NM 88210 District III	St St , Allesta, 144 00210		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aziec, NM 87410 District IV Santa Fe, NM 87505			STATE FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B2330	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP NOR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name EAST EUMONT UNIT	
PROPOSALS.) 1. Type of Well: □Oil Well □ Gas Well □ Other MAR 0 2 2016			8. Well Number	
2. Name of Operator			9. OGRID Number	
OXY USA WTP LP 3. Address of Operator			192463 10. Pool name or Wildcat	
PO BOX 4294; HOUSTON, TX 77210			EUMONT YATES 7RQN	
4. Well Location				/
	et from the NORTH line and 660 fe		line	√
Section 27 Township 19S Range 37E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3615')	
12. Check Appropriate Box to	Indicate Nature of Notice, R	eport or Other	Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOL			RK	☐ ALTERING CASING ☐ /
TEMPORARILY ABANDON				PANDA U
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEME	NT JOB	L W
OTHER:		□ Location is	ready for OCD	inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEA	SE NAME, WELL NUMBER,	API NUMBER, C	UARTER/QU	DARTER LOCATION OR
	N, TOWNSHIP, AND RANGE. PED ON THE MARKER'S SUR		ION HAS BE	EN WELDED OK
		The Real Property of the Parket of the Parke		
The location has been leveled as other production equipment.	s nearly as possible to original grou	and contour and ha	as been cleared	of all junk, trash, flow lines and
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
OCD rules and the terms of the Oper from lease and well location.	ator's pit permit and closure plan.	All flow lines, pr	oduction equip	ment and junk have been removed
All metal bolts and other materia	als have been removed. Portable b	ases have been rer	noved. (Poured	onsite concrete bases do not have
to be removed.)				
 ✓ All other environmental concer ✓ Pipelines and flow lines have be 	ns have been addressed as per OCI een abandoned in accordance with	D rules.	C All fluids h	have been removed from non-
retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribut	ion infrastructure.			
When all work has been completed,	return this form to the appropriate	District office to	schedule an ins	pection.
SIGNATURE	TITLE	ENVIRONMEN	TAL ADVISO	R_DATE 3-2-16
TYPE OR PRINT NAME _CASEY				ONE: _575-513-8289
For State Use OrNy				ADDA LV
Conditions of Approval (if any):	UnitalaTITLE_	P.E.S.		DATE 03/4/16
Conditions of Approval Hi anvi				

CY