

HOBBS OCD

MAR 14 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC ✓	API Number 3002536018 ✓
Property Name Trinity Burns Abo unit ✓	Well No. TBAU#13 ✓

Surface Location

UL - Lot 22	Section 125	Township 38E	Range 38	Feet from 2310	N/S Line N	Feet From 990	E/W Line E	County Lea ✓
-----------------------	-----------------------	------------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	------------------------

Well Status


TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD ☐	PRODUCER OIL ☐	GAS ☐	DATE 2-25-16
--	--	---	---------------------------------	--	------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure					350
Flow Characteristics					
Pull	Y / ☒	Y / ☒	Y / N	Y / ☒	CO2 ☐
Steady Flow	Y / ☒	Y / ☒	Y / N	☒ N	WTR ☒
Surges	Y / ☒	Y / ☒	Y / N	Y / ☒	GAS ☐
Down to nothing	☒ N	☒ N	Y / N	Y / ☒	Type of Fluid
Gas or Oil	Y / ☒	Y / ☒	Y / N	Y / ☒	Injected for
Water	Y / ☒	Y / ☒	Y / N	☒ N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Water on Prod. Casing. Bleed off w/ vac. truck & 24 hr test
3-6-16 Water back in PC
Fail - ✓

Signature: 	B8 3/24/16
Printed name: Justin K. L. JYK	OIL CONSERVATION DIVISION
Title: PSA	Entered into RBDMS ✓
E-mail Address: LJYK@Chevron.com	Re-test
Date: 2-25-16	
Phone: 575 704 6224	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAR 25 2016