District I 1625 N. French Dr., Hobbs, NM 88240 Phone (575) 393-6161 Fax (575) 393-6720

## HOBBS OCD

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAR 1 4 2016

RECEIVED

## BRADENHEAD TEST REPORT

or Name	110		API Number	
evron	A UNC	30	5-025-24322	*
Property Name		/	Well No.	
Vacuum Grayburg San Andres Unit			48	/
7. Surface Loca	ation			
Feet from	N/S Line	Feet From	E/W Line County	/
1330	N	1330	W Lea	/
Well Statu	us			
	CONTRACTOR SERVICE AND ADDRESS OF	PRODUCER GAS	DATE	
010	SWD OIL	GAS	3-2-16	
	Property Name  Grayburg San Andres Unit  7. Surface Loca Feet from 1330  Well State  INJECTOR	Property Name  Grayburg San Andres Unit  7. Surface Location  Feet from N/S Line 1330  Well Status  INJECTOR SWD OIL	Property Name  Grayburg San Andres Unit  7. Surface Location  Feet from N/S Line Feet From 1330  Well Status  INJECTOR SWD OIL PRODUCER GAS	Property Name  Grayburg San Andres Unit  7. Surface Location  Feet from N/S Line Feet From E/W Line County 1330 N 1330 W Lea  Well Status

## **OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing	
Pressure	0	0	WA	0	1700	
Flow Characteristics						
Puff	Y / 🐼	(O) N	Y / N	Ø/N	CO2 X WTR X	
Steady Flow	Y/60	Y / 🗞	Y/N	Y/00		
Surges	Y/Ø	Y / 🗞	Y/N	Y/®	GAS	
Down to nothing	Ø/ N	Ø/ N	Y/N	Ø/ N	Injected for	
Gas or Oil	Y / 🚳	Y / 🚳	Y / N	Y/Ø	Waterflood if applies.	
Water	Y/🔊	Y/N	Y/N	Y/(N)	MAN AND AND AND AND AND AND AND AND AND A	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

		BS 3/25/16		
Signature:	2	OIL CONSERVATION DIVISION		
Printed name: Tanner DeHaan		Entered into RBDMS . 59		
Title: FSA		Re-test		
E-mail Address: TZYR@Chevron	.com			
Date: 3-2-16	Phone: 575-390-4449			
	Witness:			