

HOBBS OCD
MAR 14 2016
RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron	USA INC ✓	API Number 30-025-31859 ✓
Property Name Vacuum Glorieta West Unit	/	Well No. 120 ✓

7. Surface Location

UL - Lot E	Section 1	Township 18S	Range 34E	Feet from 1102	N/S Line N	Feet From 1575	E/W Line E	County Lea ✓
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	-----------------

Well Status

TA'D WELL <input checked="" type="radio"/> YES NO	SHUT-IN <input checked="" type="radio"/> YES NO	INJECTOR <input checked="" type="radio"/> INJ SWD	PRODUCER OIL GAS	DATE 2-19-16
--	--	--	---------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y/ <input checked="" type="radio"/> N	Y/N	Y/N	Y/ <input checked="" type="radio"/> N	CO2 —
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/N	Y/N	Y/ <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y/ <input checked="" type="radio"/> N	Y/N	Y/N	Y/ <input checked="" type="radio"/> N	GAS —
Down to nothing	<input checked="" type="radio"/> Y/N	Y/N	Y/N	<input checked="" type="radio"/> Y/N	Type of Fluid
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/N	Y/N	Y/ <input checked="" type="radio"/> N	Injected for
Water	Y/ <input checked="" type="radio"/> N	Y/N	Y/N	Y/ <input checked="" type="radio"/> N	Waterflood if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	Entered into RBDMS BS
Title: FSA	Re-test
E-mail Address: TZYR@Chevron.com	
Date: 2-19-16	Phone: 575-390-4449
Witness:	

BS 3/25/16

MAR 28 2016