

MAR 24 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name RICE OPERATING COMPANY ✓	³ API Number 3002525211 ✓
Property Name BLINEBRY DRINKARD ✓	Well No. 22 ✓

⁷ Surface Location

UL - Lot A	Section 22	Township 22S	Range 37E		Feet from 817	N/S Line N	Feet From 965	E/W Line E	County LEA ✓
---------------	---------------	-----------------	--------------	--	------------------	---------------	------------------	---------------	-----------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE MARCH 14, 2016
NO	NO	SWD	GAS	


OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			0	259
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: ISRAEL JUAREZ	Entered into RBDMS KH 3-25-16 ✓
Title: HEAD FOREMAN	Re-test
E-mail Address: ijuarez@riceswd.com	
Date: MARCH 14, 2016	Phone: 575-393-9174
	Witness: KRISTEL HEADY

MAR 30 2016