



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp						API Number 30-025-04150			
Property Name North Monument Grayburg San Andres Unit						Well No. 11			
7. Surface Location									
UL - Lot K	Section 2	Township 20S	Range 36E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County Lea	
Well Status									
TA'D WELL YES	☒ NO	YES	☒ NO	☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 3/21/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	$\emptyset$	$\emptyset$		$\emptyset$	705
Flow Characteristics					
Puff	☒ Y / ☒ N	☒ Y / ☒ N	Y / N	☒ Y / ☒ N	CO2 ☐
Steady Flow	☒ Y / ☒ N	☒ Y / ☒ N	Y / N	☒ Y / ☒ N	WTR ☒
Surges	☒ Y / ☒ N	☒ Y / ☒ N	Y / N	☒ Y / ☒ N	GAS ☐
Down to nothing	☒ Y / ☒ N	☒ Y / ☒ N	Y / N	☒ Y / ☒ N	Type of Fluid
Gas or Oil	☒ Y / ☒ N	☒ Y / ☒ N	Y / N	☒ Y / ☒ N	Injected for
Water	☒ Y / ☒ N	☒ Y / ☒ N	Y / N	☒ Y / ☒ N	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		B8 3/30/16	
Printed name: Jim Ellison		OIL CONSERVATION DIVISION	
Title:		Entered into RBDMS CF	
E-mail Address:		Re-test	
Date: 3/21/16	Phone: 575-441-7734		
Witness: Carl Flowers			

INSTRUCTIONS ON BACK OF THIS FORM

MAR 30 2016