



State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp				API Number 30-025-05927				
Property Name North Monument Grayberg San Andres Unit				Well No. 1				
Surface Location								
UL - Lot A	Section 6	Township 20 S	Range 37 E	Feet from 1660	N/S Line N	Feet From 1660	E/W Line E	County Lea
Well Status								
TA'D WELL YES	<input checked="" type="radio"/> NO	SHUT-IN YES	<input checked="" type="radio"/> NO	INJECTOR <input checked="" type="radio"/> INJ	SWD	PRODUCER OIL	GAS	DATE 3/21/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	705
Flow Characteristics					
Puff	Y / <input checked="" type="radio"/> N	Y / N	Y / N	<input checked="" type="radio"/> Y / N	CO2 <input type="checkbox"/>
Steady Flow	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y / N	Y / N	Y / N	<input checked="" type="radio"/> Y / N	Type of Fluid
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	Injected for
Water	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS CF	
Title: Instrument Tech		Re-test	
E-mail Address:			
Date: 3/21/16	Phone: 575-441-7734		
Witness: Carl Flowers			

INSTRUCTIONS ON BACK OF THIS FORM

MAR 30 2016