

MAR 24 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp						API Number 30-035-05784					
Property Name North Monument Grayburg San Andres Unit						Well No. 13					
Surface Location											
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County		
M	29	19S	37E		660	S	660	W	Lea		
Well Status											
YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	SWD	OIL	PRODUCER	GAS	DATE
											3/23/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Ø	Ø		Ø	1060
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / Ø	Y / Ø	Y / N	Y / Ø	WTR ✓
Surges	Y / Ø	Y / Ø	Y / N	Y / Ø	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / Ø	Y / Ø	Y / N	Y / Ø	Injected for
Water	Y / Ø	Y / Ø	Y / N	Y / Ø	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS CF	
Title:		Re-test	
E-mail Address:			
Date:	Phone: 575-441-7134		
	Witness: Carol Flowers		

In C.F.

INSTRUCTIONS ON BACK OF THIS FORM

APR 04 2016