

MAR 24 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp					API Number 30-025-05910				
Property Name North Monument Grayburg San Andres Unit								Well No. 04	
Surface Location									
UL - Lot D	Section 5	Township 20 S	Range 37 E		Feet from 660	N/S Line N	Feet From 660	E/W Line W	County Lea
Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 3/23/16	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø			Ø	1660
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: J. Ellison		OIL CONSERVATION DIVISION	
Printed name: Jim Ellison		Entered into RBDMS	C.F.
Title:		Re-test	
E-mail Address:			
Date:	Phone: 575-441-7734		
	Witness: Chad Flowers		

In C.F.

INSTRUCTIONS ON BACK OF THIS FORM

APR 04 2016