

APR 0 5 2016

State of New Mexico

Energy, Minerals and Natural Resources DepartmentOil Conservation Division Hobbs District Office

RECEIVI	ED	BRADENHEAD T	EST REPORT	Γ			
The state of the s	Ope	rator Name ron USA, LLC.			API NUMBER 30-025- 25-906		
Property Name					Well No.		
Hugh					/	3 /	
		7. Surface Loc	ation				
UL-Lot Section JU	Township Range 37E	Feet from	N/S Line	Feet From	E/W Line	County	
M 14	123 376	Well Stat		330		LEA	
				DATE			
Well Status SHUT-IN		× ×					
ACI		INTERMEDIATE TO ATMOSP			ES EACH		
If bradenhead flowed wa	ater, check all of the descr	OBSERVED I	DATA			M	
	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(<u>D)Pro</u>	(D)Prod Csng (E)Tubing		
Pressure	3	MA	NA		34	250	
Flow Characteristics							
Puff	Ø/ N	Y / N	Y/1	ν	Y / N		
Steady Flow	Y/80	Y/N	Y/1	N	Y/N		
Surges	Y/Ø	Y / N	Y / 1	N	Y / N		
Down to nothing	Ø/N	Y/N	Y / 1	V	Y / N		
Gas or Oil	Y/0	Y / N	Y / 1	N	Y / N		
Water	Y / Ø	Y/N	Y / 1	Y	Y/N		
If bradenhead flowed wa	ater, check all of the descr	iptions that apply:					
CLEAR:	FRESH:	SALTY:	SULF	UR:	BLACK:		
Remarks:			INJECTING AT	TTHIS TIME	WTR,	GAS,CO2	
7,5				a 0			
				BS 4-8-16			
Signature: Joseph Collins				OIL CONSERVATION DIVISION			
Printed name: Joseph Collins				Entered into RB	DMS	BS	
Title: Production Specialist Sub-Surface				Re-test			
E-mail Address: Co	ollinsJ@chevron.com	n				The state of the	
Date: 3-25-16	Phone:	575-631-4197				上 医皮肤 维鲁	
	Witness:						
						The second secon	