

APR 06 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30-025-05656
Property Name NMGSAU	Well No. 687 07

Surface Location

UL - Lot G	Section 20	Township 19S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR IMJ	SWD	OIL	PRODUCER GAS	DATE 3-29-16
------------------	----	----------------	----	------------------------	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		12000	685
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: JD Ellison	BS 4-8-16 OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS CR
Title: Instrument Tech	Re-test
E-mail Address: JD.Ellison @ apache Corp.com	
Date: 3-29-16	Phone: 575-441-7734
Witness: Craig Flower	

APR 08 2016