

APR 06 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30-025-05732
Property Name 1/MGSAU	Well No. 407 07

Surface Location

UL Lot G	Section 29	Township 19S	Range 37E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line E	County Lea
--------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INT	SWD	PRODUCER OIL	GAS	DATE 3-30-16
------------------	----	----------------	----	------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csmg	(E) Tubing
Pressure		0		0	1075
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: JD Ellison	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS CF
Title: Instrument Tech	Re-test
E-mail Address: JD.Ellison @ apache Corp.com	
Date: 3-30-16	Phone: 575-411-7734
Witness: Carol Flower	

APR 08 2016