

Jalmar Yates Pool Unit

WELL NAME AND NUMBER Cone No. 122 Unit N 3D-025-37136

LOCATION Unit N, Section 13, T22S, R35E, 10' FSL, 2630' FWL, Lea Co. NM

OPERATOR Melrose Operating Company

DRILLING CONTRACTOR United Drilling, Inc.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and had conducted deviation tests and obtained the following results:

<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>
<u>1/4° 513'</u>	<u> </u>	<u> </u>
<u>1/4° 996'</u>	<u> </u>	<u> </u>
<u>1/2° 1525'</u>	<u> </u>	<u> </u>
<u>1/2° 1996'</u>	<u> </u>	<u> </u>
<u>1° 2495'</u>	<u> </u>	<u> </u>
<u>1° 2995'</u>	<u> </u>	<u> </u>
<u>1° 3523'</u>	<u> </u>	<u> </u>
<u>1-1/2° 3995'</u>	<u> </u>	<u> </u>

Drilling Contractor United Drilling, Inc

By: George A. Aho
George A. Aho


Title: Business Manager

Subscribed and sworn to before me this 16th day of January,
2006.

Carlene Martin
Notary Public

My Commission Expires: 10/08/08

Chaves New Mexico
County State



K