•	Jalma Vates Pool Unit	,
WELL NAME AND NUMBER Cor	ne No. 123 Unit K	30-025-37225
LOCATION 2630' FSL, 2460'	FWL, Section 13, T22S, R35F	E, Lea County NM
OPERATOR Melrose Operating	ng Company	
DRILLING CONTRACTOR Unite	ed Drilling, Inc.	· · · · · · · · · · · · · · · · · · ·
of the drilling contractor ducted deviation tests and	y certifies that he is an au who drilled the above descr obtained the following resu	ibed well and had con-
Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
1/4° 507'		
1/2° 1039'		
1/4° 1507'		
3/4° 2038'		
1° 2507'		*
1-1/4° 3006'		
1-1/2° 3503'		
1-1/4° 4005'		
1-1/4 4005	·	
	Drilling Contractor Unit	ed Drilling, Inc.
		ge/A. Aho
	Title: Busi	iness Manager
Subscribed and sworn to be	fore me this $3/3$ day of (	Aloku.
20 05.	Carla	e Mailu
	Notar \(\cap\)	ry Public/
My Commission Expires: /0//	08/08 County	New Mexico
		28212828
	and the second	<b>%</b>
		(2 Recent 2)
	1/	Hopps