

HOBBS OCD

MAR 14 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

30-025-36248

25

Operator Name

CHEVRON USA WC

Property Name

Trinity 1300's Abo Unit

Surface Location

Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
27	125	38E	38	2310	S	330	E	LOA

Well Status

YES	NO	YES	NO	NO	SWD	OIL	PRODUCER	GAS	DATE
									3-6-16


OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	φ	φ	2/1	φ	200
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Gas Bleed down to nothing
PASS

BS 4-26-16

Signature: 	OIL CONSERVATION DIVISION
Printed name: Justin Wall	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: LBYK@Chevron.com	
Date: 3-5-16	Phone: 575 704 6224
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

APR 27 2016