

HOBBS OCD

MAR 14 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA INC ✓	API Number 3002536451 ✓
Property Name ✓ Trinity Bonis ABO unit ✓	Well No. 5 ✓

Surface Location

U.S. Lot ✓ 23	Section 12S	Township 38E	Range 38	Feet from 2310	N/S Line N	Feet from 1650	E/W Line W	County Lea
-------------------------	-----------------------	------------------------	--------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	NO	YES	NO	INJ	SWD	OIL	PRODUCER	GAS	DATE
	NO		NO	INJ					3-5-16


OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	φ	φ	N/A	φ	200
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	N / N	N / N	Y / N	N / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

PASS

BS 4-26-16

Signature: 	OIL CONSERVATION DIVISION
Printed name: Justin Wall	Entered into RBDMS ups
Title: FSA	Re-test
E-mail Address: LJYK@Chevron.com	
Date: 3-5-16	
Phone: 575-704-6224	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

IN
ups

APR 27 2016