

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

		Texlan	d Petroleu	Name m-Hobbs ,	LLC		1		30-025-229	934
Property Name State A-29							Well No. # 0 7			
				7. §	Surface Locati	on				
UL - Lot	Section 29	Township 18S	Range 38E		Feet from 660'	N/S Line		t From	E/W Line	County
<i>y</i>	29	105	38E		Well Status	-		850'	West	Lea
*** 11	G		SHUT-IN		PRODUCING			T		
Well	Status		No		PRODUCING	41	12 1 b	E		
Adio	OPEN	BRADENH		ERMEDIATE	TO ATMOSPHE	RE INDIVIDUA		15 MINUT	ES EACH	
					SERVED DA	ТА				
bradenhead	I flowed water		of the description		Intoum(2)	(C)Intown Pro	d	(D) D	1.0	(EVE.1.)
ressure		(A)Surf-Interm (I		(B)Interm(I)	(B)Interm(1)-Interm(2)		(C)Interm-Prod		d Csng	(E)Tubing
low Characteristics		1)	Ø					15	45
Puff		Y	/ ()	C)/ N	V /	Y / N		Y / N	
Steady I		-	Y/A		70	Y / N			Y / N	
Surges			Y / 🔕	Y / 65		Y / N			Y / N	
Down to nothing			Ø/ N	(Ŋ/ N		Y / N			Y / N	
Gas or Oil			Y / 🔇	Y / (5)		Y / N			Y / N	
Wate	Water		Y/8	◎ / N		Y / N		-	Y / N	
f bradenhead CLEAR	l flowed water	FRES	of the descriptio		LTY	SUL	ELIB		BLACK	*/
LEAK		TRES		SA		302	····		DLACK	
Signature:									4.26-	
Signature:			Δ.					IL CON	SERVATIO	N DIVISION
	2:		Raul	806	781 562	<u>5</u>	Entere	IL CON:	SERVATIO	
Printed name				806	781 562	5		IL CON:	SERVATIO	N DIVISION
Printed name	ess: vsmith	@texpetr	o.com		781 562	ó	Entere	IL CON:	SERVATIO	N DIVISION
Signature: Printed name Title: E-mail Addre Date:		@texpetr			781 562	5	Entere	IL CON:	SERVATIO	N DIVISION