

HOBBS OGD

APR 25 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

03913

Operator Name	CHEVRON USA Midcontinent	API Number	300254303
Property Name	WEST LOUGHTON unit	Well No.	61

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
12	8	17S	36E	2310	5	1980	W	LEA ✓

Well Status

Well Status	Active	SHUT-IN	PRODUCING	DATE	
			INS	4-14-16	CY

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	0	0	1400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature:	Urich Merch	OIL CONSERVATION DIVISION
Printed name:	Urich Merch	Entered into RBDMS
Title:	Inspector	Re-test
E-mail Address:	Urich@chevron.com	
Date:	4-14-16	
Phone:	970-903-2603	
Witness:		

APR 27 2016