

APR 2 2 2016

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

T A	The state of the s	OC	Operator Na CIDENTAL PER		/	TRETOR		³ API Number 30-025-28349	1
Property Name SOUTH HOBBS (G/SA) UNIT								Well No.	
				7. St	ırface Locatio	n			
UL - Lot	Section 9 ,	Township 19S	Range 38E		Feet from 75	N/S Line NORTH	Feet From 1205	E/W Line WEST	County /
				V	Well Status				
YES TA'D	WELL NO) YES	SHUT-IN	inj	INJECTOR S	SWD @	PRODUCER GAS		OATE -/C
									n VX

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	NIA	NA	NIA	31 PM	318 B
Flow Characteristics		1			
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR_
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Waterflood if applies.
Water	Y/N	Y / N	Y / N	Y/N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed	d down or continuous build up if applies.
Did Not Have surface casing	Bryan Lollin 575-441-9739
Signature: Mendy Sohmon	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: Phone: 806-592-6280	
Witness:	