

APR 27 2016

State of New Mexico

Energy, Minerals and Natural Resources Department rict Office

	Oil Conservation I	Division	Hobbs	Disti
RECEIVED	BRADENH	HEAD T	EST RI	E PO l

REC	EIVE		Operator Nam	SA, LLC.	F REPOR'	<u>T</u>	API NUMB 30-025-	/
							22109	,
	Property Name R. E. Cok NCT A				8	ell No.		
				7. Surface Location	1			
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
K	16	225	37 E	2130	5	2130	W	LEA V
				Well Status				
Well	Status		SHUT-IN	PRODUCING		DATE		- · A
****	Status			X		4-13-16		OVX

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	D	NA	NA	25	65
Flow Characteristics			///		
Puff	Y / 🚱	Y / N	Y / N	Y / N	
Steady Flow	Y / 🚱	Y / N	Y / N	Y / N	
Surges	Y / Ø	Y / N	Y/N	Y / N	
Down to nothing	Ø/ N	Y / N	Y/N	Y / N	
Gas or Oil	Y/Ø	Y / N	Y/N	Y / N	
Water	Y / Ø	Y/N	Y / N	Y / N	

If bradenhead flowe	ed water, check all of the descript	ions that apply:			
CLEAR:	FRESH:	SALTY:	SULFUR:	BLACK:	

INJECTING AT THIS TIME ____ WTR, __ Remarks:

4.28-16 Joseph Collins OIL CONSERVATION DIVISION Signature: **Joseph Collins** Entered into RBDMS Printed name: Title: **Production Specialist Sub-Surface** Re-test E-mail Address: CollinsJ@chevron.com Date: 4-13-16 575-631-4197 Phone: Witness: