

APR 27 2016

## State of New Mexico

## **Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office**

BRADENHEAD TEST REPORT

REOF	Operator 1		ENHEAD I	ESI KE	TOKI		A 1	DI NILIMDI	ED		
Chevron USA, LLC.						API NUMBER <b>30-025-</b>					
Cherron Cort, Elec.							31538				
Property Name							7	Well No.			
R.R. Sims A						2 /					
			7. Surface Loca	ation						. 1	
VIL-Lot Section Township Range 235 37 £		Feet from			N/S Line Feet			E/W Line	County	¥ /	
N 04 23.	5 37 É		1660		5	1654		W	LEA		
			Well Stati	us							
Well Status	SHUT-IN		PRODUCING		4-	4-14-16		Plugged N		2 1	
							V		- W		
OPEN BRAD	ENHEAD AND INT				VIDUALI	LY FOR 15 M	INUTES F	EACH			
If bradenhead flowed water, check	k all of the description		OBSERVED D	ATA							
	A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing		
Pressure											
Flow Characteristics											
Puff	Y / N	Y/N			Y / N		Y / N		-		
Steady Flow	Y / N	Y / N			Y / N		Y / N		-		
Surges	Y / N	Y / N		1	Y / N		Y / N				
Down to nothing	Y / N	Y / N			Y / N		Y / N				
Gas or Oil	Y/N	N Y/N			Y / N		Y / N		1		
Water	Y/N		Y / N	Y / 1			Y / N				
If bradenhead flowed water, check	all of the description	ne that anni	1×7*								
	RESH:				SULFU	EUD.		BLACK:			
					Delle	Direction of the second of the					
Remarks:				INJEC	TING AT	THIS TIME	W	ΓR,(	GAS,CO2	2	
WEll is	Dlugged										
Well 13	1.4.55										
							0				
						/	72	4-28	5/4		
Signature: Joseph Collins						OIL CONSERVATION DIVISION					
Printed name: Joseph Collins						Entered into RBDMS					
Title: Production Specialist Sub-Surface						Re-test					
E-mail Address: CollinsJ@	chevron.com										
Date: 4-14-16	Phone: 57:	Phone: 575-631-4197								4	
	Witness:										
										740	