HOBBS OCD

APR 1 8 2016

State of New Mexico **Energy, Minerals and Natural Resources Department**Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

OCCIDENTAL PERMIAN, LTD						30-025-35452		
Property Name NORTH HOBBS (G/SA) UNIT /					11-15	Well No. 834 ✓		
		7. Su	rface Locati	ion				
UL - Lot Section Township Range O 32 18-S 38-E		Feet from		N/S Line	Feet From	E/W Line	County	
0 32	Well State		SOUTH	2365	EAST	LEA /		
YES NO		NO INJ		SWD OH		AS 05	Pr /	
OBSERVED DATA								
	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)P	rod Csng	(E)Tubing	
Pressure	500					376711	380-52	
Flow Characteristics	Characteristics				TAKE NO			
Puff	(Y) N	Y / N		Y / N	V	Y / N	CO2 WTR	
Steady Flow			N	Y / N	V	Y / N	GAS GAS	
Surges	YIN	Y/N		Y / N	V	Y / N	Type of Fluid	
Down to nothing	Ø N	Y/N		Y / N	V	Y / N	Injected for Waterflood if	
Gas or Oil	YI	Y/N		Y / N		Y / N applies.		
Water	Y/N	Y / N		Y / N	V	Y / N		
Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. Sheeps Af to Mothery Daniel Colum 575 - 318.57067								
Signature: 700 hom.					BS 4 29-16			
Mendy Am					OIL CONSERVATION DIVISION			
Printed name: MENDY JOHNSON					Entered into RBDMS			
Title: ADMINISTRATIVE ASSOCIATE					Re-test			
E-mail Address: mendy_johns	on@oxy.com			First Day	OF THE PER		AS CHAR	
Date: APR 1 3 2016 Phone: 806-592-6280					to each			
	Witness:					MESSE		