

APR 11 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT	*API Number 30-025-05407
Property Name LPU	Well No. 70

7. Surface Location									
UL - Lot M	Section 06	Township 17S	Range 37E	Feet from 660	N/S Line FSL	Feet From 614	E/W Line FWL	County CEA	

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJECTOR INJ	SWD	OIL	PRODUCER	GAS	DATE 3-30-16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1500
Flow Characteristics					
Pull	Y/N	X/X	X/X	Y/N	CO2 —
Steady Flow	Y/N	X/X	X/X	Y/N	WTR —
Surges	Y/N	X/X	X/X	Y/N	GAS —
Down to nothing	Y/N	X/X	X/X	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	X/X	X/X	Y/N	
Water	Y/N	X/X	X/X	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

~~0-0-0-0-0~~

Signature: Urich Mendoza	B 5-12-16
Printed name: Urich Mendoza	OIL CONSERVATION DIVISION
Title: Pumper	Entered into RBDMS CB
E-mail Address: umh@CHEVRON.COM	Re-test
Date: 3-30-16	Phone: 970-903-2603
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

MAY 12 2016

OK
JW
BMB