

415-16

HOBBS OCD
APR 18 2016
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT ✓	API Number 30-025-03787 ✓
Property Name LSA ✓	Well No. 26 ✓

7. Surface Location

UL - Lot N	Section 36	Township 16S	Range 36E	Feet from 000	N/S Line S	Feet from 1980	E/W Line W	County LEA ✓
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHIFT-IN YES ☐ NO ☒	INJECTOR INJ ✓	SWD ☐	PRODUCER OIL ☐	GAS ☐	DATE 3-25-16 <i>CH</i>
--	---	--------------------------	---------------------------------	--	------------------------------	-------------------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure ✓	0	0	N/A	0	1350
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Uriah Mendoza</i>	OIL CONSERVATION DIVISION
Printed name: URIAH MENDOZA	Entered into RBDMS CB
Title: Pumper	Re-test
E-mail Address: umbb@chevron.com	
Date: 3-25-16	Phone: 970-903-2603
Witness:	

BB 5-12-16

IN
guts
MAY 12 2016