

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING	² API Number 30-025-33752
Property Name CARROCK - MALTAMAR - UNIT	Well No. 265

² Surface Location

UL - Lot C	Section 24	Township 17S	Range 32E	Feet from 660	N/S Line N	Feet From 2022	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------


Well Status

TA'D WELL YES	NO	SHUT-IN NO	YES	INJECTOR NO	SWD NO	OIL PRODUCER NO	GAS NO	DATE 5/13/16
-------------------------	-----------	----------------------	------------	-----------------------	------------------	---------------------------	------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	NA	NA	0	2350
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.



Signature: Eddie J. Jaramillo	OIL CONSERVATION DIVISION
Printed name: Eddie J. Jaramillo	Entered into RBDMS
Title: PRODUCTION SPECIALIST	Re-test
E-mail Address:	
Date: 5/13/16	Phone: (575) 370-9686
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

[Handwritten Signature]