

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING	API Number 30-025-00527
Property Name CAPROCK MALJAMAR UNIT	Well No. 14


Surface Location									
UL - Lot I	Section 13	Township 17S	Range 32E	Feet from 1980	N/S Line S	Feet From 660	E/W Line E	County Lea	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 5/13/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	2A	2A	0	2450
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Water flood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.



Signature: Eddie J. Jaramillo	OIL CONSERVATION DIVISION
Printed name: Eddie J. Jaramillo	Entered into RBDMS
Title: PRODUCTION SPECIALIST	Re-test
E-mail Address:	
Date: 5/13/16	Phone: (575) 370-9686
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

[Handwritten Signature]