

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING	API Number 30-025-00529
Property Name CAPROCK MALTAMAR - UNIT	Well No. 23

Surface Location

UL - Lot 0	Section 13	Township 17S	Range 32E	Feet from 660	N/S Line S	Feet from 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------


Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	PRODUCER NO	DATE 5/13/16
-------------------------	----------------------	-----------------------	-----------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ	φ	NA	φ	2400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.



Signature: Eddie J. Jaramillo	OIL CONSERVATION DIVISION
Printed name: Eddie J. Jaramillo	Entered into RBDMS
Title: PRODUCTION SPECIALIST	Re-test
E-mail Address:	
Date: 5/13/16	Phone: (575) 370-9686
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

IN SMD