

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING				API Number 30-025-01482			
Property Name CAPROCK MALJAMAR UNIT				Well No. 79			
2. Surface Location							
UL - Lot 0	Section 19	Township 17S	Range 33E	Feet from 990	N/S Line S	Feet From 2310	E/W Line E
							County LEA


Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 5/13/16
-------------------------	----------------------	-----------------------	------------------	------------------	-----------------------	------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	0	2450
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.



Signature: Eddie J. Jaramillo		OIL CONSERVATION DIVISION
Printed name: Eddie J. Jaramillo		Entered into RBDMS
Title: PRODUCTION SPECIALIST		Re-test
E-mail Address:		
Date: 5/13/16	Phone: (575) 370-9686	
Witness: [Signature]		

INSTRUCTIONS ON BACK OF THIS FORM