

HOBBS OCD

MAY 25 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

CHEVRON, U.S.A.	Operator Name	API Number 30 025 12236
DOLLARHIDE	Property Name West Dollarhide Drinkard unit	Well No. WDDU-37 37

7. Surface Location

UL - Lot p	Section 29	Township 5024	Range E038	Feet from 660	N/S Line S	Feet From 660	E/W Line E	County LEA
---------------	---------------	------------------	---------------	------------------	---------------	------------------	---------------	---------------

24S 38E

Well Status

Well Status Active	SHUT-IN NO	PRODUCING INJ ✓	DATE 4-28-16
-----------------------	---------------	--------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure			NA		1375 PSI
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: ___ CO2	INJECTING AT THIS TIME ___ X ___ WTR, ___ GAS,
---------------------	--

Signature: Dalton Pinkston	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS CF
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 4-28-2016	Phone: 432-208-1086
Witness: Carl Flowers	