

MAY 20 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Legacy Reserves Operating LP1		API Number 3002510682	
Property Name SPAU		Well No. 47	

Surface Location									
UL - Lot 6	Section 9	Township 23S	Range 37E	Feet from 1980	NS Line N	Feet from 1980	E/W Line E	County Leq	

Well Status								
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 4/25/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	40			40	40
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A-S95

BS 5-26-16

Signature: Steven Dittman		OIL CONSERVATION DIVISION	
Printed name: Steven Dittman		Entered into RBDMS BS	
Title:		Re-test	
E-mail Address:			
Date: 4/25/16	Phone: 432-312-4757		
Witness:			