

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAY 20 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Burgundy Oil & Gas of NM Inc		API Number 36-025-06067	
Property Name Skusss Grayburg Unit		Well No. 1	

UL - Lot K	Section 12	Township 20S	Range 37E	Feet from 1985	N/S Line S	Feet From 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒	SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 4/26/16
--	--	--	------------------------------	---	------------------------

Active

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	ϕ		ϕ	75
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	CO2 ☐
Steady Flow	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	WTR ☒
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	GAS ☐
Down to nothing	☐ Y ☒ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Type of Fluid
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	Injected for
Water	☒ Y ☐ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Failure water is coming out of surface valve, steady stream

BS 5-26-16

Signature: Cindy Campbell	OIL CONSERVATION DIVISION
Printed name: Cindy Campbell	Entered into RBDMS CF
Title: Production Accountant	Re-test
E-mail Address: ccampbell.bogi@att.net	
Date: 4/26/16	Phone: 432-684-4033, X-205
Witness: Carl Flowers	

INSTRUCTIONS ON BACK OF THIS FORM