

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

MAY 25 2016

BRADENHEAD TEST REPORT

RECEIVED

CHEVRON, U.S.A.	Operator Name	API Number 30 025 12382
DOLLARHIDE	Property Name West Dollarhide Drinkard Unit	Well No. WDDU-84 84

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
H	5	5025	E08	1656	N	990	E	LEA

255

38E

Well Status

Well Status CTA	SHUT-IN NO	PRODUCING INJ	DATE 4-28-16
--------------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure		N/A	N/A		0 PSI
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: CO2	INJECTING AT THIS TIME ___X___ WTR, ___ GAS,
-----------------	--

Signature: Dalton Pinkston	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS CF
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 4-28-2016	Phone: 432-208-1086
Witness: Carl Flowers	