

HOBBS OCD

MAY 25 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON, U.S.A.	API Number 30 025 31489
Property Name DOLLARHIDE West Dollarhide Drinkard Unit	Well No. WDDU 122 122

7. Surface Location

UL - Lot K	Section 32	Township 24S	Range 38E	Feet from 2055	N/S Line S	Feet From 1981	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status Active	SHUT-IN NO	PRODUCING INJ	DATE 4-28-16
-----------------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure			N/A		1450 psi
Flow Characteristics					
Puff	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: CO2	INJECTING AT THIS TIME ___X___ WTR, ___ GAS,
-----------------	--

Signature: Dalton Pinkston	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS CF
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 4-28-2016	Phone: 132-208-1086
Witness: Carl Flowers	