

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAY 25 2016

BRADENHEAD TEST REPORT

RECEIVED

CHEVRON, U.S.A.	Operator Name	API Number 30 025 31999
-----------------	---------------	----------------------------

DOLLARHIDE	Property Name West Dollarhide Drinkard Unit	Well No. WDDU-139 139
------------	--	--------------------------

7. Surface Location									
UL - Lot C/3	Section 5	Township 5025	Range E048		Feet from 420	N/S Line N	Feet From 1900	E/W Line W	County LEA

Well Status				
Well Status Active	SHUT-IN NO	PRODUCING INJ ✓	DATE 4-29-16	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure		V/A	V/B		PSI
Flow Characteristics					1425
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: ___ CO2 no witness when test was done	INJECTING AT THIS TIME ___X___ WTR, ___ GAS,
--	--

Signature: Dalton Pinkston	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 4-29-2016	Phone: 432-208-1086
Witness:	