

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAY 25 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON, U.S.A.		API Number 30 025 32772	
Property Name DOLLARHIDE West Dollarhide Drinkard unit		Well No. WDDU 151	

7. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
B	5	5025	EE 3		640	N	2000	E	LEA

255 38E

Well Status

Well Status (TA)	SHUT-IN NO	PRODUCING INJ ✓	DATE 4-27-16
---------------------	---------------	--------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(d)Prod Csgng	(E)Tubing
Pressure		NA	NA		0-281 1375 psi
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: CO2 NO WITNESS	INJECTING AT THIS TIME ___X___ WTR, ___ GAS,
-----------------------------------	--

Signature: Dalton Pinkston	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 4-28-2016	Phone: 432-208-1086
Witness:	