

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAY 25 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON, U.S.A.		API Number 30 025 33413	
Property Name DOLLARHIDE West Dollarhide Drinkard unit		Well No. WDDU 156 156	

7. Surface Location

UL - Lot I	Section 32	Township 24S	Range 38E	Feet from 2000	N/S Line S	Feet From 1200	E/W Line E	County LEA
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status (TA)	SHUT-IN NO	PRODUCING INJ	DATE 4-28-16
---------------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure		N/A	N/A		1000 psi
Flow Characteristics					packerfluid
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: CO2	INJECTING AT THIS TIME ___X___ WTR, ___ GAS,
-----------------	--

Signature: Dalton Pinkston	OIL CONSERVATION DIVISION
Printed name: DALTON PINKSTON	Entered into RBDMS CF
Title: FSA	Re-test
E-mail Address: DPIN@CHEVRON.COM	
Date: 4-28-2016	Phone: 432-208-1086
Witness: Carl Flowers	