

JUN 13 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 30-025-06325	
Property Name EBDU		Well No. 3	

1. Surface Location									
UL - Lot M	Section 1	Township 21S	Range 37E	Feet from 2970	N/S Line FSL	Feet From 330	E/W Line FWL	County LEA	

Well Status

TA'D WELL ☒ YES	☐ NO	SHUT-IN ☐ YES	☐ NO	☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 4-27-16
--	-----------------------------	---	-----------------------------	---	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	D			D	1500
Flow Characteristics					
Flow	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	CO2
Steady Flow	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	WTR
Surges	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	GAS
Down to nothing	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	Type of Fluid
Gas or Oil	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	Injected for
Water	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down, or continuous build up if applies.

**IN
GMP**

Signature: DC		OIL CONSERVATION DIVISION	
Printed name: DAVID CUMMINGS		Entered into RBDMS	
Title: SR PUMPER		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness:		