

JUN 13 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 56 30 025 06334
Property Name EBDU		Well No. 56

7. Surface Location									
UL - Lc U	Section 21S	Township R37E	Range 37E	Feet from 1610	N/S Line FSL	Feet from 810	E/W Line FNL	County LEA	

Well Status

YES	NO	YES	NO	INJ	SWD	OIL	PRODUCER	GAS	DATE 4/27/16
-----	----	-----	----	-----	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Line (1)	(C)Term(2)	(D)Prod Csg	(E)Flow
Pressure	✓	0		-	1390
Flow Characteristics					
Surf	Y/N	Y/N	Y/N	Y/N	CC1 -
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surge	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	Injected for Waterflood
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding flow or continuous build up if applicable.

SURF 0 IN 15 SEC

IP
JMB

Signature: DAVID CUMMINGS		OIL CONSERVATION DIVISION	
Print Name: DAVID CUMMINGS		Entered into RBDM3	
Title: SR PUMPER		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness:		