

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 13 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP	API Number 30 025 06479
Property Name EBDU	Well No. 18

Surface Location									
UL - Lot A	Section 11	Township 21S	Range 37E	Feet from 660	N/S Line FNL	Feet From 330	E/W Line FEL	County LEA	

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 4-14-16
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1475
Flow Characteristics					
Puff	☒ Y / ☐ N	☒ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	CO2 ☐
Steady Flow	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	WTR ☐
Surges	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	GAS ☐
Down to nothing	☒ Y / ☐ N	☒ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	Type of Fluid
Gas or Oil	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	Injected for
Water	☐ Y / ☒ N	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☒ N	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*TD
GMB*

Signature: <i>David Cummings</i>	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test
E-mail Address:	
Date: 4-14-16	
Phone:	
Witness: <i>Krista Heady</i>	